

## PORT OF FLEETWOOD

NOTICE to MARINERS 08 of 2017

### New positions of buoys

**Mariners are hereby advised** that temporary unlit white marker buoys have been removed and buoy no25 & 26 have been repositioned.

New position Green buoy no25 - Lat 53 55.201 N  
Long 003 00.411 W

New position Red buoy no26 Lat 53 55.207 N  
Long 003 00.351 W

For any further advice or assistance please call Fleetwood dock on vhf channel 12 or telephone 01253 872351.

ABP Fleetwood  
Port Office  
Fleetwood  
Lancashire  
FY7 6PP

David Taylor  
Deputy Harbour Master

22 July 2017