



## PORT OF FLEETWOOD

NOTICE to MARINERS 11 of 2019

### **No. 24 buoy reported unlit**

**Mariners are hereby advised** that the No.24 buoy has been reported and confirmed as unlit.

Mariners are therefore advised to navigate with extreme caution until such time as the light has been repaired.

ABP Fleetwood  
Port Office  
Fleetwood  
Lancashire  
FY7 6PP

David Taylor  
Deputy Harbour Master

24<sup>th</sup> April 2019

**Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.**