



PORT OF FLEETWOOD

NOTICE to MARINERS 10 of 2019

No. 05 buoy

Mariners are hereby advised that the No.05 buoy has been put back on its charted position but has been reported unlit.

All mariners are requested to navigate with caution within the vicinity of this buoy until the problem can be rectified.

LNtM 03 of 2019 is hereby cancelled.

ABP Fleetwood
Port Office
Fleetwood
Lancashire
FY7 6PP

Dave Taylor
Deputy Harbour Master

22/03/19 March 2019

Owners, Agents, Charterers, Fishermen and Recreational Sailing Organisations should ensure that the contents of this notice are made known to the masters or persons in charge of their vessels or craft.